Qty:

20 Um:

Each



Date: Tuesday, 05/08/2008 12:57:58 PM User Melanie Fauteux

**Process Sheet** 

**Drawing Name** 

Part Number

Material

**Due Date** 

**Drawing Number** 

Project Number

**Drawing Revision** 

: WEARPAD

: D35641

: N/A

: D

: D3564 REVD

: 12/08/2008

Customer Job Number

: CU-DAR001 Dart Helicopters Services

S.O. No. :

Type

: 40988

**Estimate Number** : 12781

P.O. Number

: 05/08/2008 This Issue

Prsht Rev. : NC

: 11 First Issue : 39286

Previous Run

Written By

Checked & Approved By

Comment

: Est Rev:A Est Rev:B New Issue 07-03-08 ec As per Rev C 07-07-09 JLM

: SMALL /MED FAB

08-08

Est Rev:C As per Rev D 07-09-09 JLM Verified By:EC

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description: 304/316 Sheet .063

1.0

2.0

M304S16GA

Comment: Qty.: 1.1550 sf(s)/Unit Total: 23.1000 sf(s)

> M304S16GA Stainless steel sheet 0.063" thick Batch: (0.063) 8 - 8 - 8 8-8-6

WATER JET

FLOW WATER JET



Comment: FLOW WATER JET

1-Cut as per Dwg D3564

Dwg Rev: \_\_\_\_\_

Prog Rev:

\*\*\*\*\*(D3564-1F)\*\*\*\*\*

B 8-8-6

2-Deburr if necessary

HB 8-8-6

3.0

INSPECT PARTS AS THEY COME OFF MACHINE



B8-8-6

Comment: INSPECT PARTS AS THEY COME OFF MACHINE

4.0

QC8

QC2

SECOND CHECK

NC BRAKE



Comment: SECOND CHECK

5.0 BRAKE NO



Comment: NC BRAKE

Deburr if necessary


Form on Brake as per Dwg D3564 using Jigs DT 8179 and DT 8155



SB 08/08/19



Date: Tuesday, 05/08/2008 12:57:58 PM User Melanie Fauteux **Process Sheet** Drawing Name: WEARPAD Customer: CU-DAR001 Dart Helicopters Services Job Number: 40988 Part Number: D35641 Job Number: Seq. #: Machine Or Operation: Description: Form Joggles (2) as per Dwg D3564 on brake using Jig DT 8157 6.0 QC5 INSPECT WORK TO CURRENT STEP Comment: INSPECT WORK TO CURRENT STEP Ensure joggle as per dwg D3429 7.0 LARGE FAB 1 Comment: LARGE FABRICATION RESOURCE 1 Qty Description Batch M108631 2059B Hardcoat A/R Weld hardcoat as per Dwg D3437 VISUAL INSPECTION OF GROUND WELDS 8.0 QC10 Comment: VISUAL INSPECTION OF GROUND WELDS 9.0 QC5 INSPECT WORK TO CURRENT STEP Comment: INSPECT WORK TO CURRENT STEP 10.0 Comment: POWDER COATING Powder Coat Grey Sandtex (Ref: 4.3.5.6) as per QSI 005 4.3 START TIME: OVEN TEMPERATURE: FINISH TIME: 11.0 QC3 POWDER COAT/CHEMICAL CONVERSION 12.0 PACKAGING 1 PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1 Identify and Stock Location: [=P-] 6 Page 2 Form: rprocess



Date:

Tuesday, 05/08/2008 12:57:58 PM

User:

. Melanie Fauteux

**Process Sheet** 

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: WEARPAD

Job Number: 40988

Part Number: D35641

Job Number:



Seq. #:

Machine Or Operation:

Description:

13.0

QC21

FINAL INSPECTION/W/O RELEASE






MF 08-08-2/

Comment: FINAL INSPECTION/W/O RELEASE

Job Completion





DART AEROSPACE LTD	Work Order:	40788
Description: Wearshoe	Part Number:	D3564-1
Inspection Dwg: D3564 Rev: C		Page 1 of 1

## FIRST ARTICLE INSPECTION CHECKLIST

	x	First Article	F	rototyp	е	
Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
3.227	+/-0.010	3.33+	*			
2.432	+/-0.010	2.437	*			
2.50	+/-0.030	2,50	×			
6.000	+/-0.010	6.000	Je			
12.104	+/-0.010	12,104	×			
18.000	+/-0.010	18.000	8			
18.00	+/-0.030	18.00	7			
9.00	+/-0.030	9.∞	×			
11.50	+/-0.030	11.50	X			
0.300 x 0.300	+/-0.010	304 × 304				
Ø0.188	+0.005/-0.001	190	٧.			
R0.375	+/-0.010	375	×			
0.063	+/-0.010	,059	×			
	200	Audited by:	dali	Pro	totype Approva	
Date:	8-8-6	Date: C	स्विक		Dat	e: N/A
Rev Date A 07.09.06	Change New Issue				Revised KJ/JLM	

